

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Figure 1




Figure 2




Figure 3




Figure 4




Figure 5




Figure 6





Figure 7



[illegible]

170

Figure 9




Figure 10




Figure 11




FIGURE 12




FIGURE 13




FIG. 1 is a perspective view of a rectangular frame assembly 15. The assembly includes a main frame 426 with four rectangular openings 430. Each opening contains a grid-like structure 428. The frame is secured by four corner fasteners 462. A central cross member 452 is visible. A cable 482 is connected to the bottom right corner. A label 480 points to the overall assembly.

FIGURE 15




FIGURE 16




FIGURE 17




FIGURE 18




FIGURE 19




FIGURE 20




FIGURE 21




FIGURE 22




FIGURE 23




FIGURE 24.




FIGURE 25




Figure 26:

